



GENERAL NOTES

- 1.) ☒ = LEAVE MATERIAL AND MACHINE AFTER HEAT TREAT.
- 2.) T.S. = THEORETICAL SHARP.
- 3.) SURFACE FINISH: 125 OR BETTER
- 4.) BREAK ALL SHARP EDGES
- 5.) ENGRAVE DRAWING NO. ON PART

UNLESS SPECIFIED

0.XXXX = ±.001"
 0.XXX = ±.005"
 0.XX = ±.015"
 0.X = ±.030"
 ANGLE: ±.5 Deg.



10 Tower Road Winneconne, WI 54986
 PROTO-1 MANUFACTURING L.L.C.
 RESERVES PROPRIETARY RIGHTS
 TO THIS DRAWING AND THE DATA
 SHOWN THEREON. SAID DRAWING
 AND DATA ARE NOT TO BE USED OR
 REPRODUCED FOR ANY REASON
 WITHOUT THE WRITTEN CONSENT
 OF PROTO-1 MANUFACTURING L.L.C.
WWW.PROTO1MFG.COM

SRM-336

Main Assembly

DRAWN BY: _____
 CHECKED BY: _____

SCALE: 1:24 SHEET 1 OF 1

THIRD ANGLE PROJECTION



JOB QTY



DRAWING NUMBER

SRM3-A01

REV.

A

GAGE #:

FIXTURE #:

REPRODUCED FROM:

EST. WEIGHT (lbs): 2964.6